Monday, 11/09/2006 10:04:14 AM

User

Linda Lacelle

**Process Sheet** 

Customer Job Number : CU-DAR001 Dart Helicopters Services

: 28063

**Estimate Number** 

: 10288

P.O. Number

: NIA

This Issue Prsht Rev. : 11/09/2006

S.O. No. : NIA

: NIA : 28063

: SMALL /MED FAB

Type

**Drawing Number Project Number** 

**Drawing Name** 

**Part Number** 

**Drawing Revision** Material

**Due Date** 

:NIA

: D25771

: 18/09/2006

: WEARPLATE

: D2577 REV E

Each

Previous Run Written By

First Issue

Checked & Approved By

Comment

: Est: E

02.09.24 Re-format; Incorporated D2577-101/-11 KJ/

RF

est F

06.09.11

now waterjet

EC

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description: 1010/1025/A21/6aA SHEET

1.0

M1010S16GA

1010/1025/A21/6aA SHEET

0.8474 sf(s)/Unit Total: 42.3675 sf(s)

2.0

WATER JET

Comment: Qty.:



Comment: FLOW WATER JET

1-Cut as per Dwg D2577 (D2577-101 detail)

Dwg Rev:\_\_

2-Deburr if necessary

Prog Rev. E

86 05 12

QC2

3.0

Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0

5.0

QC8

SECOND CHECK



Comment: SECOND CHECK

BRAKE NC

NC BRAKE




Comment: NC BRAKE

1-Form on brake as per Dwg D2577 using DT8155 and DT8179

2-Form joggle as per Dwg D2577 using DT8157

3-Identify as D2577-1



Monday, 11/09/2006 10:04:14 AM Date: Linda Lacelle User: **Process Sheet** Drawing Name: WEARPLATE Customer: CU-DAR001 Dart Helicopters Services Job Number: 28063 Part Number: D25771 Job Number: Seq. #: Description: **Machine Or Operation:** 4-Deburr if nesasary INSPECT WORK TO CURRENT STEP 6.0 QC5 WORK TO CURRENT STEP Comment: INSPE LARGE FAB 1 LARGE FABRICATION RESOURCE 1 7.0 Cp(06.11.29 Comment: LARGE FABRICATION RESOURCE 1 Weld hard surface using DT8308A & DT8308B as per Dwg D2577 Description Batch Qtv A/R 7560 Hardcoat Rod m102756 M101217 VISUAL WELDING INSPECTION QC9 8.0 **Comment: VISUAL WELDING INSPECTION** POWDER COATING POWDER COATING Comment: POWDER COATING Powder Coat Grey Sandtex (Ref: 4.3.5.6) as per QSI 005 4.3 INSPECT POWDER COAT/CHEMICAL CONVERSION 10.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 11.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: QC21 12.0 Comment: FINAL INSPECTION/W/O RELEASE N 26.12 Job Completion

Each

Dart Aerospace Ltd. Tuesday, 8/1/2006 11:29:37 AM Kim Johnston User: **Process Sheet** : WEARPLATE Customer : CU-DAR001 Dart Helicopters Services **Drawing Name** Job Number : 28063 **Estimate Number** : 10288 : D25771 P.O. Number **Part Number** : 8/1/2006 . D2577 REV E **Drawing Number** This Issue S.O. No. : Prsht Rev. : NC Project Number : N/A : // : PURCHASED PARTS : E First Issue Type **Drawing Revision** : 26350 Material **Previous Run** 50 Um: : 8/25/2006 Qty: **Due Date** Written By Checked & Approved By : Est: E 2.09.24 Re-format; Incorporated D2577-101/-11 KJ/ Comment RF WaterSel **Additional Product** OS 09 13 Job Number: Description: Seq. #: Machine Or Operation: PURCHASING 1.0 PG Comment: PURCHASING Issue P/O: Email or Ship DXF file to vendor Laser Cut per Dwg D2577 flat pattern D2577-101 Material release note required 2.0 D25771F Wearplate Fwd Comment: Qty.: 1.0000 Each(s)/Unit Total: 50.0000 Each(s) WEAR PLATE FWD 3.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Receive & Inspect For Transit Damage Ensure material release note is attached 4.0 QC6 DIMENSIONAL CHECK

Comment: DIMENSIONAL CHECK

Inspect dimensions per template D2577-101T

5.0

NC BRAKE



Comment: NC BRAKE

1-Form on brake as per Dwg D2577 using DT8155 and DT8179

2-Form joggle as per Dwg D2577 using DT8157

3-Identify as D2577-1

# Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector	
						:		-		
NCR:		,	WORK ORDE	ER NON-CONFORMAN	ICE (NCR	)	. ,			
		Description of NC	Corrective Action Section B Verification		ation	Approval	Approval			
DATE	STEP	Section A	Initial Design Mgr	Action Description  Design Mgr	Sign & Date	Sectio		Approval Design Mgr	Approval QC Inspector	
									+	
	·									
							u.			
									•	
Part No	):	PAR #:	Fault Category	/: NCR:	Yes No	DQA:		Date:		
NOTE: D	ate & initial a	all entries			QA: N/C CIG	osed:		Date:		

H:\forms\Quality Assurance\approved forms\NCRWO revC

Date: Tuesday, 8/1/2006 11:29:37 AM User: Kim Johnston **Process Sheet Drawing Name: WEARPLATE** Customer: CU-DAR001 Dart Helicopters Services Job Number: 28063 Part Number: D25771 Job Number: Seq. #: Description: Machine Or Operation: 4-Deburr if nesasary INSPECT WORK TO CURRENT STEP 6.0 QC5 Comment: INSPECT WORK TO CURRENT STEP 7.0 LARGE FAB 1 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 Weld hard surface using DT8308A & DT8308B as per Dwg D2577 Qty Description Batch A/R 7560 Hardcoat Rod VISUAL WELDING INSPECTION 8.0 QC9 Comment: VISUAL WELDING INSPECTION 9.0 POWDER COATING POWDER COATING Comment: POWDER COATING Powder Coat Grey Sandtex (Ref: 4.3.5.6) as per QSI 005 4.3 INSPECT POWDER COAT/CHEMICAL CONVERSION 10.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION PACKAGING 1 PACKAGING RESOURCE #1 11.0 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 12.0 DC DOCUMENT CONTROL Comment: DOCUMENT CONTROL

Inspection Level 21

Job Completion




# **Dart Aerospace Ltd**

N

W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC inspector				
				G.							

NCR:		W	WORK ORDER NON-CONFORMANCE (NCR)								
	STEP	Description of NC		Corrective Action Section B	Verification	Approval	Approval				
DATE		Section A	Initial Design Mgr	Action Description  Design Mgr	Sign & Date	Section C	Approval Design Mgr	Approval QC Inspector			
					1		-:				
		,									
				<u></u>							
	:						, "				

Part No:	PAR #:	Fault Category:	NCR:	Yes	No	DQA: _	 Date:	W-14
NOTE: Date & initial all entries				QA: N	1/C C	losed:	 Date:	



00 






D2577-3 WEARSHOE

D2577-11 AND D2577-13 RESPECTIVELY POWDER COAT GREY (4.3.5:6) PER DART QSI 005 4.3 TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED


D2941-300	et .
SHWAYDER WEAPADS —	CEOTION: A A
(8 PLACES) \	<u>SECTION_A-A</u> SCALE_1:5
\ ·	SCALL 1.5
\ \	R2.00 ~
1 4 6 1	20044 700 (055)
Ag Z - 1.50 (TYP)	D2941-300 (REF) REMOVE POWDER
	8:13 - REMOVE POWDER COAT FROM THESE
DE HITTER (TYP)	SURFACES
SHOP CONTROLLER WITHOUT A PETURAL TO D2577-23 WEARSHOE	
D25四层 202577—23 WEARSHOE	
DAJAIG & ODEST ALA MERICANIO	
MAK包有的 D2577-11 AND D2577-13 R	
FINISH: POWDER COAT GREY (4.3.5.6) PI	ER DART QSI 005 4.3
TOLERANCES ARE PER DART QSI 018 UNL	

DESIGN	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
CHECKE	(ED APPROVED	DRAWING NO. REV. E
^	专	D2577 SHEET 1 OF 5
DATE		TITLE SCALE
00.0	00.09.22	WEARSHOE 1:10
≻	96.09.16	NEW ISSUE
Φ	96.12.04	ADD HARDCOAT WELDS
ဂ	97.05.30	CHANGE HOLES TO OBROUNDS
0	98.08.17	CORRECTED DIMENSIONS ON -1 & -3
ш	00.09.22	ADD D2577-101/-11/-13 INCORPORATE DE09176




ROSPACE L

## D2577-7 FLAT PATTERN



## D2577-7 LONGITUDINAL BEND



## D2577-7 WEARSHOE

UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE

BREAK ALL SHARP CORNERS 0.010 TO 0.020

MATERIAL: AISI 1010-1025 OR ASTM A36/A366/A569/A570

SERIES STEEL 0.063 THICK

FINISH: POWDER COAT GREY (4.3.5.6) PER DART QSI 005 4.3 TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED



0 B



오

ESIGN ESIGN	C C	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
HECKED	APPROVED	DRAWING NO.
*	-6	D2577 SHEET 4
ATE		THE
0.09.22		WEARSHOE

REV.

OF 5







DESIGN	DRAWN BY	DART AEROSPACE LT HAWKESBURY, ONTARIO, CANADA	D
CHECKED	APPROVED APPROVED	DRAWING NO. D2577 SH	REV. E
DATE	1	TITLE	SCALE
00.09.22		WEARSHOE.	1:10

#### DETAIL B (SCALE 1:1)






#### DETAIL C (SCALE 1:1)



#### SECTION D-D (SCALE 1:1)



SHOP COPY RETURN TO ENGINEERING UNCONTROLLED COPY SUBJECT TO AMENDMENT WITHOUT NOTICE

WORK ORDER NO 28063

Copyright © 1996 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

DART AEROSPACE LTD	Work Order: 28%3
Description:	Part Number: 2577-1
nspection Dwg: \Rev:	Page 1 of 1

# FIRST ARTICLE INSPECTION CHECKLIST

X First Article X Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
0.320×0.300	+1-0.010	0.550×0.30	1	4 4 ,	Vern	
2.43	+1-0.030	2.44	<b>V</b>		vern	-
6.000	+1-0.010	6.001	<b>Y</b>		Vecn	·
3.182	+1-0.010	3.185			NEKN	
36.000	41-0.010	36.000	·\		Monsuring	tape
			<u> </u>		•	- £
				7.		`*** '
			2			
				9		
				,		
						·
						·
					Town:	
		·	i			
						·
		*				

Measured by: M.M.	Audited by:	1	Prototype Approval:	
Date: 6.09.12	Date:	Re-1012	Date:	

Rev	Date	Change	Revised by	Approved
Α		New Issue	KJ/JLM	

